

July 29, 2002

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D.C. 20555

10 CFR 50.73

Gentlemen:

**TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT (SQN)  
UNIT 2 - DOCKET NO. 50-328- FACILITY OPERATING LICENSE  
DPR 79 - LICENSEE EVENT REPORT (LER) 50-328/2002003**

The enclosed report provides details concerning an automatic reactor trip from a high generator stator cooling water temperature resulting from a failure of a raw cooling water isolation valve. This event is being reported, in accordance with 10 CFR 50.73(a)(2)(iv), as an event that resulted in an automatic actuation of the reactor protection system. This letter is being sent in accordance with NRC RIS 2001-05.

Sincerely,

**Original signed by**

Richard T. Purcell

Enclosure

cc (Enclosure):

INPO Records Center  
Institute of Nuclear Power Operations  
700 Galleria Parkway  
Atlanta, Georgia 30339-5957

Estimated burden per response to comply with this mandatory information collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records Management Branch (T-6 E6), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by Internet e-mail to bjs1@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

**LICENSEE EVENT REPORT (LER)**

(See reverse for required number of  
digits/characters for each block)

**1. FACILITY NAME**

Sequoyah Nuclear Plant (SQN) UNIT 2

**2. DOCKET NUMBER**

05000328

**3. PAGE**

1 OF 07

**4. TITLE**

Automatic Reactor Trip Resulting from a Generator Stator Cooling Water High Temperature Caused by a Raw Cooling Water Valve Failure

**5. EVENT DATE**

MO	DAY	YEAR
05	31	2002

**6. LER NUMBER**

YEAR	SEQUENTIAL NUMBER	REV NO
2002	003	00

**7. REPORT DATE**

MO	DAY	YEAR
07	29	2002

**8. OTHER FACILITIES INVOLVED**

FACILITY NAME	DOCKET NUMBER
FACILITY NAME	DOCKET NUMBER

**9. OPERATING  
MODE**

1

**11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)****10. POWER  
LEVEL**

071

20.2203(a)(2)(ii)

50.36(c)(2)

50.73(a)(2)(v)(B)

OTHER  
Specify in Abstract below or in NRC Form  
366A**12. LICENSEE CONTACT FOR THIS LER****NAME**

James Proffitt

**TELEPHONE NUMBER (Include Area Code)**

(423) 843-6651

**13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT**

CAUSE	SYSTEM	COMPONENT	MANU- FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU- FACTURER	REPORTABLE TO EPIX
X	TJ	VLV	P340	Y					

**14. SUPPLEMENTAL REPORT EXPECTED**

YES (If yes, complete EXPECTED SUBMISSION DATE)	NO
-------------------------------------------------	----

**15. EXPECTED  
SUBMISSION DATE**

MONTH	DAY	YEAR

**16. ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)**

On May 31, 2002, at 0116 Eastern Daylight Time the Unit 2 turbine tripped followed by a reactor trip as a result of an actuation of the main generator stator cooling water failure circuit. Prior to the trip, Operations personnel observed increased temperature on the generator stator cooling water system. Indications show that the generator stator cooling water temperature reached the setpoint then actuated as required. The main control room operators took appropriate actions to stabilize the reactor in hot standby (Mode 3). The generator stator cooling water high temperature was the result of a raw cooling water isolation valve failure causing low flow to the stator cooling water system heat exchanger. The raw cooling water valve was replaced.

**LICENSEE EVENT REPORT (LER)**

FACILITY NAME (1)	DOCKET	LER NUMBER (6)			PAGE (3)
Sequoyah Nuclear Plant (SQN) Unit 2	05000328	YEAR	SEQUENTIAL NUMBER	REVISION	2 OF 7
		2002	— 002	— 00	

**NARRATIVE** (If more space is required, use additional copies of NRC Form 366A) (17)

**I. PLANT CONDITION(S)**

Unit 2 was in Mode 1 at approximately 71 percent reactor power. Operations was in the process of increasing power.

**II. DESCRIPTION OF EVENT**

**A. Event:**

On May 31, 2002 at 0116 Eastern Daylight Time (EDT) the turbine tripped followed by a reactor trip as a result of an actuation of the main generator stator cooling water failure circuit (EIIIS Code TJ). Prior to the trip, Operations personnel observed increased temperature on the generator stator cooling water system. Operations personnel were trying to ensure proper cooling water flow was available to the stator cooling water system when the trip occurred. Indications show that the generator stator cooling water temperature reached the setpoint then actuated as required. The main control room operators took appropriate actions to stabilize the reactor in hot standby (Mode 3).

**B. Inoperable Structures, Components, or Systems that Contributed to the Event:**

None.

**C. Dates and Approximate Times of Major Occurrences:**

May 30, 2002 at ~1709 EDT      Stator Temperatures begin to increase. Generator tied online at about this time.

May 31, 2002 at 2146 EDT      The generator stator temperature high alarms. Operations begins to investigate and take actions to ensure proper cooling flow to the generator stator cooling system.

May 31, 2002 at 0115 EDT      The generator stator cooling system failure alarm actuates.

# LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET	LER NUMBER (6)			PAGE (3)
Sequoyah Nuclear Plant (SQN) Unit 2	05000328	YEAR	SEQUENTIAL NUMBER	REVISION	3 OF 7
		2002 -	002 -	00	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

May 31, 2002 at 0116 EDT      The generator stator cooling failure turbine trip alarm and reactor trip alarm annunciated in the main control room.

May 31, 2002 at 0133 EDT      Operations completed actions to secure equipment and stabilize plant in Mode 3.

**D. Other Systems or Secondary Functions Affected:**

None.

**E. Method of Discovery:**

The main generator stator cooling water failure circuit alarm and subsequent turbine and reactor trips annunciated on the main control room panels.

**F. Operator Actions:**

Control room operators responded to the event in accordance with plant procedures. They promptly diagnosed the plant condition, took the actions necessary to stabilize the unit, and maintained the unit in hot standby, Mode 3.

**G. Safety System Responses:**

The plant responded to the turbine and reactor trips, as designed with the exception of a Rod Cluster Control Assembly (RCCA) that showed a delayed insertion into the core below approximately 17 steps withdrawn during the reactor trip.

## III. CAUSE OF THE EVENT

**A. Immediate Cause:**

The immediate cause of the event was the actuation of the high generator stator cooling water failure circuit. The high temperature was the result of loss of raw cooling water flow to the stator cooling water heat exchanger.

# LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET	LER NUMBER (6)			PAGE (3)
Sequoyah Nuclear Plant (SQN) Unit 2	05000328	YEAR	SEQUENTIAL NUMBER	REVISION	4 OF 7
		2002 -	002 -	00	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

## **B. Root Cause:**

The root cause of the event was the loss of raw cooling water flow to the generator stator cooling water system resulting from a manual isolation supply valve to stator cooling water heat exchanger blocking flow due to internal damage. The valve disk was found split down the shaft.

## **C. Contributing Factors:**

A contributing factor to this event was the decision by Operations personnel to apply supplemental force to the valve, rather than evaluating the cause of the difficulty in opening the valve.

## **IV. ANALYSIS OF THE EVENT**

The plant safety systems responses during and after the unit trip were bounded by the responses described in the Final Safety Analysis Report.

## **V. ASSESSMENT OF SAFETY CONSEQUENCES**

Based on the above Analysis of The Event, this event did not adversely affect the health and safety of plant personnel or the general public.

## **VI. CORRECTIVE ACTIONS**

### **A. Immediate Corrective Actions:**

An investigation was performed to determine the cause of the loss of cooling water to the generator stator cooling water system. It was determined that the raw cooling water isolation valve did not open as indicated. An analysis of the valve failure is provided below.

### **B. Corrective Actions to Prevent Recurrence:**

The raw cooling water valve was replaced.

# LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET	LER NUMBER (6)			PAGE (3)
Sequoyah Nuclear Plant (SQN) Unit 2	05000328	YEAR	SEQUENTIAL NUMBER	REVISION	5 OF 7
		2002 --	002 --	00	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

Guidance on the use of supplemental force and expectations for personnel performance when field components do not perform as expected is being developed.

## VII. ADDITIONAL INFORMATION

### A. Failed Components:

A raw cooling water butterfly valve (Henry Pratt Model 2FII) failed. This valve is an 8-inch, hand wheel operated, valve, which is the raw cooling water inlet isolation valve to the Unit 2 stator cooling water heat exchanger. During restart activities following the refueling outage, Operations personnel tried to open the raw cooling water valve to the generator stator cooling water system. When the stem would not turn because the disk was bound into the seat, a supplemental force was used to force stem rotation.

The supplemental force caused the pre-existing crack in the valve disk to crack completely down the disk. Additional use of the supplemental force caused the shaft pin to rotate into the disk hole, splitting the disk apart and allowing flow through the center of the disk.



After the disk was pushed into the rubber seat far enough to add additional resistance to rotation, the shear key sheared and the valve operator turned freely to its stop. This gave the operators the impression that the valve was full open and the valve position indicator was reading incorrectly.

### B. Previous LERs on Similar Events:

A review of previous reportable events for the past three years did not identify any similar events.

# LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET	LER NUMBER (6)			PAGE (3)
Sequoyah Nuclear Plant (SQN) Unit 2	05000328	YEAR	SEQUENTIAL NUMBER	REVISION	6 OF 7
		2002 -	002 -	00	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

## C. Additional Information:

The rod position indicator (RPI) trace of Shutdown Bank A RCCA at core location L-11 showed a delayed insertion into the core below approximately 17 steps withdrawn during the reactor trip. However, as explained below, it does not appear that the indicated delayed insertion was the result of excessive swelling of the rodlet tips (i.e., generic industry issue). Troubleshooting continues to rule out other possible causes such as debris, mechanical interference with RCCA/drive shaft, or fuel assembly bowing.

Previous eddy current wear measurements were made on the Unit 2 RCCAs during the Cycle 7 refueling outage. This RCCA had the lowest wear measured on any Unit 2 RCCAs. This RCCA has accumulated approximately 13.4 effective full power years of exposure. The possible crack indications measured were approximately 5.3 inches (longest indication) on 5 rodlets. The possible crack indications provides the extent of hairline axial cracking of the rodlet tips because of fluence-induced swelling of the Ag-In-Cd absorber. The possible crack indications of this RCCA was on the lower end of the bulk of indications measured on the Unit 2 RCCAs. This RCCA has not been in Control Bank D since the Cycle 7 refueling outage and, should not have accumulated excessive additional fluence on the rodlet tips.

During the U2C11 refueling outage, RCCA drag testing showed normal values both before the unlatching at the start of refueling and after the post-refueling latching. RCCA drop time testing following the refueling outage showed normal trace characteristics with fast speed from trip to dashpot entry. The characteristic "bounce" was present indicating full insertion, proving operability. Subsequent additional rod drop time testing was performed after the problem RPI L-11 response was detected which showed acceptable Technical Specification drop time. The delayed insertion of the RCCA into the core could not be repeated during testing. Therefore, the condition observed for this RCCA during the reactor trip was determined acceptable. The rod inserted sufficiently to perform its function; therefore, this is not considered a safety system functional failure.

# LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET	LER NUMBER (6)			PAGE (3)
Sequoyah Nuclear Plant (SQN) Unit 2	05000328	YEAR	SEQUENTIAL NUMBER	REVISION	7 OF 7
		2002 —	002 —	00	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

Given these facts, this RCCA does not appear to be a good candidate for excessive swelling of the rodlet tips that might lead to binding in the dashpot region during rod insertion and result in delayed full-insertion times.

Based on industry information related to problems with aging of RCCAs, the Unit 2 RCCAs are scheduled to be replaced during the next refueling outage.

## D. Safety System Functional Failure:

This event did not result in a safety system functional failure in accordance with NEI 99-02.

## VIII. COMMITMENTS

None.